2501 01 00

	Section 1	PRODUCT AND COM	PANY ID	ENTIFICATIO	N	
PRODUCT	NUMBER				HMIS CODES	
2501				Fl	alth ammability activity	2* 4 0
MANUFACT THE S KRYLC Cleve	DN* Interior/Ex CURER'S NAME CHERWIN-WILLIAM DN Products Gro eland, OH 44115 PREPARATION	up		rown EMERGENCY (216) 566	TELEPHONE NO. -2917 N TELEPHONE NO.	·
======================================	Section 2 CAS No.	COMPOSITION/INF INGREDIENT	ORMATIO	N ON INGRED	IENTS VAPOR PRES	SURE
14	74-98-6	Propane ACGIH TLV OSHA PEL	2500 1000	mqq מממ	76	50 mm
6	106-97-8	Butane ACGIH TLV OSHA PEL			76	50 mm
2	100-41-4	Ethylbenzene ACGIH TLV ACGIH TLV OSHA PEL OSHA PEL	100 125	ppm ppm STEL ppm	7.	1 mm
10	1330-20-7	Xylene ACGIH TLV ACGIH TLV OSHA PEL OSHA PEL	100 150 100 150	ppm ppm STEL ppm	5.	9 mm
39	67-64-1		500	ppm	18	30 mm
9	78-93-3	Methyl Ethyl Ke ACGIH TLV ACGIH TLV OSHA PEL	tone 200 300 200	ppm ppm STEL ppm	7	'0 mm
7	108-65-6	OSHA PEL 1-Methoxy-2-Pro ACGIH TLV OSHA PEL	Not Av	ppm STEL cetate ailable ailable	1.	8 mm
0.1	1333-86-4	Carbon Black ACGIH TLV OSHA PEL	3.5 3.5	mq/m3		

Continued on page 2

page 2 Section 3 -- HAZARDS IDENTIFICATION \_\_\_\_\_ ROUTES OF EXPOSURE INHALATION of vapor or spray mist. EYE or SKIN contact with the product, vapor or spray mist. EFFECTS OF OVEREXPOSURE EYES: Irritation. SKIN: Prolonged or repeated exposure may cause irritation. INHALATION: Irritation of the upper respiratory system. May cause nervous system depression. Extreme overexposure may result in unconsciousness and possibly death. SIGNS AND SYMPTOMS OF OVEREXPOSURE Headache, dizziness, nausea, and loss of coordination are indications of excessive exposure to vapors or spray mists. Redness and itching or burning sensation may indicate eye or excessive skin exposure. MEDICAL CONDITIONS AGGRAVATED BY EXPOSURE None generally recognized. CANCER INFORMATION For complete discussion of toxicology data refer to Section 11. Section 4 -- FIRST AID MEASURES \_\_\_\_\_ \_\_\_\_\_ EYES: Flush eyes with large amounts of water for 15 minutes. Get medical attention. SKIN: Wash affected area thoroughly with soap and water. Remove contaminated clothing and launder before re-use. INHALATION: If affected, remove from exposure. Restore breathing. Keep warm and quiet. Do not induce vomiting. INGESTION: Get medical attention immediately. Section 5 -- FIRE FIGHTING MEASURES \_\_\_\_\_ LEL UEL 1.0 13.1 FLASH POINT Propellant < 0 FEXTINGUISHING MEDIA Carbon Dioxide, Dry Chemical, Foam UNUSUAL FIRE AND EXPLOSION HAZARDS Containers may explode when exposed to extreme heat. Application to hot surfaces requires special precautions. During emergency conditions overexposure to decomposition products may cause a health hazard. Symptoms may not be immediately apparent. Obtain medical attention. SPECIAL FIRE FIGHTING PROCEDURES Full protective equipment including self-contained breathing apparatus should be used. Water spray may be ineffective. If water is used, fog nozzles are preferable. Water may be used to cool closed containers to prevent pressure build-up and possible autoignition or explosion when exposed to

Continued on page 3

extreme heat.

2501

2501	page 3
Section 6 ACCIDENTAL RELEASE MEASURES	
STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED Remove all sources of ignition. Ventilate the area. Remove with inert absorbent.	
Section 7 HANDLING AND STORAGE	
<pre>STORAGE CATEGORY Not Available PRECAUTIONS TO BE TAKEN IN HANDLING AND STORAGE Keep away from heat, sparks, and open flame. Vapors will av readily and may ignite explosively. During use and until all vapors are gone: Keep area ventils smoke - Extinguish all flames, pilot lights, and heaters - Turn electric tools and appliances, and any other sources of ignitic Consult NFPA Code. Use approved Bonding and Grounding proce Contents under pressure. Do not puncture, incinerate, or ex temperature above 120F. Heat from sunlight, radiators, stoves and other heat sources could cause container to burst. Do not internally. Keep out of the reach of children.</pre>	ated - Do not n off stoves, on. edures. xpose to , hot water,
Section 8 EXPOSURE CONTROLS/PERSONAL PROTECTION	
PRECAUTIONS TO BE TAKEN IN USE Use only with adequate ventilation. Avoid contact with skin and eyes. Avoid breathing vapor and Wash hands after using. This coating may contain materials classified as nuisance pp (listed "as Dust" in Section 2) which may be present at hazard only during sanding or abrading of the dried film. If no spec are listed in Section 2, the applicable limits for nuisance du TLV 10 mg/m3 (total dust), 3 mg/m3 (respirable fraction), OSHA (total dust), 5 mg/m3 (respirable fraction). Removal of old paint by sanding, scraping or other means may dust or fumes that contain lead. Exposure to lead dust or fume brain damage or other adverse health effects, especially in ch pregnant women. Controlling exposure to lead or other hazardor requires the use of proper protective equipment, such as a prop respirator (NIOSH approved) and proper containment and cleanup information, call the National Lead Information Center at 1-80 (in US) or contact your local health authority. VENTILATION Local exhaust preferable. General exhaust acceptable if the materials in Section 2 is maintained below applicable exposure Refer to OSHA Standards 1910.94, 1910.107, 1910.108. RESPIRATORY PROTECTION If personal exposure cannot be controlled below applicable is ventilation, wear a properly fitted organic vapor/particulate is approved by NIOSH/MSHA for protection against materials in Sect When sanding or abrading the dried film, wear a dust/mist r approved by NIOSH/MSHA for dust which may be generated from th underlying paint, or the abrasive.	articulates ous levels ific dusts sts are ACGIH PEL 15 mg/m3 y generate es may cause ildren or us substances perly fitted . For more 0-424-LEAD e exposure to limits by respirator tion 2. espirator
Continued on page 4	

2501	page 4			
PROTECTIVE GLOVES None required for normal application of aerosol products where minimal skin contact is expected. For long or repeated contact, wear chemical resistant gloves. EYE PROTECTION Wear safety spectacles with unperforated sideshields. OTHER PRECAUTIONS Intentional misuse by deliberately concentrating and inhaling the contents can be harmful or fatal.				
Section 9 PHYSICAL AND CHEMICAL PROPERTIES				
PRODUCT WEIGHT 6.43 lb/gal 770 g/l SPECIFIC GRAVITY 0.77 BOILING POINT    BOILING POINT 0.77   MELTING POINT <0 - 302 F	olvents			
Section 10 STABILITY AND REACTIVITY				
STABILITY Stable CONDITIONS TO AVOID None known. INCOMPATIBILITY None known. HAZARDOUS DECOMPOSITION PRODUCTS By fire: Carbon Dioxide, Carbon Monoxide HAZARDOUS POLYMERIZATION Will not occur				

\_\_\_\_\_

Section 11 -- TOXICOLOGICAL INFORMATION

## CHRONIC HEALTH HAZARDS

Ethylbenzene is classified by IARC as possibly carcinogenic to humans (2B) based on inadequate evidence in humans and sufficient evidence in laboratory animals. Lifetime inhalation exposure of rats and mice to high ethylbenzene concentrations resulted in increases in certain types of cancer, including kidney tumors in rats and lung and liver tumors in mice. These effects were not observed in animals exposed to lower concentrations. There is no evidence that ethylbenzene causes cancer in humans.

\_\_\_\_\_\_

There is no evidence that ethylbenzene causes cancer in humans. Carbon Black is classified by IARC as possibly carcinogenic to humans (group 2B) based on experimental animal data, however, there is insufficient evidence in humans for its carcinogenicity.

Methyl Ethyl Ketone may increase the nervous system effects of other solvents.

Prolonged overexposure to solvent ingredients in Section 2 may cause adverse effects to the liver, urinary, blood forming and reproductive systems.

Reports have associated repeated and prolonged overexposure to solvents with permanent brain and nervous system damage.

74-98-6 P	Propane				
		LC50 LD50	RAT RAT	4HR	Not Available Not Available
106-97-8 E	Butane			4	
		LC50 LD50	RAT RAT	4HR	Not Available Not Available
100-41-4 E	Ethylbenzene			4.110	
		LC50 LD50	RAT RAT	4HR	Not Available 3500 mg/kg
1330-20-7 X	Xylene	LC50	RAT	4HR	5000 ppm
		LD50	RAT	4 <b>Π</b> Κ	5000 ppm 4300 mg/kg
67-64-1 A	Acetone	таго		4.115	
		LC50 LD50	RAT RAT	4HR	Not Available 5800 mg/kg
78-93-3 M	Methyl Ethyl	Ketone		4	
		LC50 LD50	RAT RAT	4HR	Not Available 2740 mg/kg
108-65-6 1	1-Methoxy-2-E			2	
	-	LC50 LD50	RAT	4HR	Not Available 8500 mg/kg
1333-86-4 0	Carbon Black	UUUU	RAT		8500 mg/kg
			RAT	4HR	Not Available
		LD50 ======	RAT =======		Not Available
Section 12 ECOLOGICAL INFORMATION					

ECOTOXICOLOGICAL INFORMATION No data available.

Continued on page 6

2501	page 6
Section 13 DISPOSAL CONSIDERATIONS	s
WASTE DISPOSAL METHOD Waste from this product may be hazardous as Conservation and Recovery Act (RCRA) 40 CFR 261 Waste must be tested for ignitability to det hazardous waste numbers. Do not incinerate. Depressurize container. with Federal, State/Provincial, and Local regul	1. termine the applicable EPA Dispose of in accordance
Section 14 TRANSPORT INFORMATION	
No data available.	
Section 15 REGULATORY INFORMATION	
SARA 313 (40 CFR 372.65C) SUPPLIER NOTIFICATION	N
CAS No. CHEMICAL/COMPOUND	% by WT % Element
100-41-4 Ethylbenzene 1330-20-7 Xylene 78-93-3 Methyl Ethyl Ketone	2 10 9
CALIFORNIA PROPOSITION 65 WARNING: This product contains chemicals kr California to cause cancer and birth defects or TSCA CERTIFICATION All chemicals in this product are listed, or on the TSCA Inventory.	r other reproductive harm.
Section 16 OTHER INFORMATION	
This product has been classified in accordan	nce with the bazard criteria

This product has been classified in accordance with the hazard criteria of the Canadian Controlled Products Regulations (CPR) and the MSDS contains all of the information required by the CPR.

The above information pertains to this product as currently formulated, and is based on the information available at this time. Addition of reducers or other additives to this product may substantially alter the composition and hazards of the product. Since conditions of use are outside our control, we make no warranties, express or implied, and assume no liability in connection with any use of this information.